Service Quotation Number 11053996

PLEASE REFER TO THIS NUMBER WHEN ORDERING

Date 08/11/2015

Customer

Calif Inst of Technology Mail Code 103-6 1200 East California Blvd. Pasadena, CA 91125-0001 Contact Bruce Brunschwig (626) 395-2420 bsb@caltech.edu

RMA#

Quote Valid To: 09/10/2015

PO# TBA

Item	Description	Qty	Unit Price	Ext. Price	
1.0	TURBO PUMP REPAIRS	1	800.00	800.00	
	Catalog # #PS303				
	PN PM P02 801 G SN 14141843				
	MINIMUM COST FOR REFURBISHMENT ON A TMU 071P				
	The standard inspection turn around time for this repair is 15 business days.				

REFURBISHMENT INCLUDES: *Incorporation of product improvements *Pump remanufactured to factory specifications *Replacement of bearings, o-rings and consumable parts *Like new, 12-month warranty

Replacement of damaged or worn metal and other non-consumable parts is not included.

Please note: If following our inspection and quotation you opt not to proceed with the repair, you will be responsible for an evaluation fee of \$250.00 each.

Surcharges Taxes (9.00%) Sub Total	\$ \$ \$ \$	800.00 0.00 0.00 800.00
Order Total	\$	800.00

If you choose not to proceed with the repair, there will be an evaluation fee assessed. This estimate is contingent upon final test & assembly.

Return freight charges are not included.

Terms for delivery and payment:DeliveryFCA OriginPaymentNet 30

This quotation includes all of the terms and conditions on both the face and attached documents hereof. The attached detail terms and conditions of sale Pfeiffer document version (November 2013) are incorporated by reference as fully as if set forth on the face of this form. This offer may be accepted only on the exact terms set forth herein and no other agreement in any way modifying any of said terms and conditions shall be accepted or binding on Pfeiffer unless accepted in writing. Quoted by: Akara Mao



Pfeiffer Vacuum Inc. 24 Trafalgar Square Nashua, NH 03063 Tel : 1-800-248-8254